

# DO YOU KNOW?

The difference between Schrader's EZ-sensor® and an OER Sensor

## EZ-sensor

Comes blank and must be programmed to the specific make, model and year of the vehicle using a compatible TPMS programming tool (see back page). Once programmed, the EZ-sensor® performs identically to the OER sensor.

- **1 SKU**  
Combines 314.9, 315 & 433 MHZ

- **PROGRAMMABLE**

Compatible with most tools on the market you may already own

- **STEM OPTIONS**

Rubber Snap-In  
Aluminum Clamp-In  
Black Anodized Clamp-In

- **OE QUALITY**

From the OE Supplier



Part #33500

### STEP-BY-STEP INSTALLATION

1. Program sensors with a compatible TPMS programming tool (see back page).
2. Install the programmed EZ-sensors.
3. Perform the factory TPMS relearn procedure on the vehicle.

## OER-sensor

(Original Equipment Replacement)

Comes pre-programmed to the specific make, model and year of a vehicle. A vehicle relearn procedure must be performed after a sensor is installed, often requiring a TPMS tool with OBD capability.

- **1 for 1 REPLACEMENT SENSOR**
- **READY OUT OF THE BOX**
- **OE FIT, FORM AND FUNCTION**



### STEP-BY-STEP INSTALLATION

1. Identify the correct OER sensor part online at [www.SchraderSensors.com](http://www.SchraderSensors.com) or your preferred TPMS catalog.
2. Install the OER sensors.

**REMEMBER** “Programming” a sensor is different than “re-learning” a vehicle.

Regardless of the sensor manufacture, each new sensor ID must be learned to the vehicle.

# COMPATIBLE TOOLS

Program EZ-sensor® with any of these TPMS Tools



## Schrader *Private Label Tools* TPMS Solutions



## BARTEC USA



## ATEQ



## Snap-on



Tool could require programming software.

## Schrader TPMS Solutions

**TECH LINE:**  
**1.800.288.1804**  
[www.SchraderSensors.com](http://www.SchraderSensors.com)

A high quality TPMS diagnostic tool can:

- Diagnose all TPMS sensors
- Program EZ-sensor®
- Provide audit reports
- Perform relearn procedures
- Include OBDII capabilities

For the best TPMS coverage and service, ensure that your TPMS tool has the latest software update.